<b>Work Order ID 58242</b> Sunday, May 02, 2010 1:11:02 PM						Page 1
Item ID: D3914-7 Revision ID: Item Name: Rib		Accept			•	Start Stop
Start Date: 5/3/2010 Start Qty: 6.00 Required Date: 5/7/2010 Req'd Qty: 6.00 Reference:			Cust Item ID: Customer:			
Approvals: Process Plan: MF	Date: <u>///-5- @</u>	Tooling: SPC (Y/N):	Date:Date:			Stop
Sequence ID/ Operation Work Center ID Description	, <u></u>	Set Up/ Run Hours	Draw Draw Number Rev.	Plan Ac Code Qt	cept Reject	et Reject Insp. Number Stamp
Draw Nbr Revision Nbr						Ţ.
D3914 A	1					:
Large Fab Memo		0.00		6		
Large Fab 1- Cut tub	e as per dwg D3914 nd remove identification mar	Sf	HO 5-03	at to the second	•	•
QC5- Inspect part com QC QC Quality Control	pleteness to step on W/O	00.00 S volus	5/03		16	
120 Identify as per dwg & S Packaging Memo Packaging	Stock Location: WA	0.00 SAC	) 5-03	(a	6)	

<b>Dart Aerospace Lt</b>	d
--------------------------	---

	•											
W/O:			W	ORK ORDER CHANG	GES							
DATE	STEP	PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Cate	egory:	NCR:	Yes N	o DQ	<b>A</b> :	_ Date: _	<u> </u>		
Resolution: Disposition:					QA: N/C Closed: Date:							
NCR:			WORK ORE	ER NON-CONFORM	ANCE	(NCR)						
DATE	STEP	Description of NC	Corrective Action Section B			Verifica			Approval	Approval		
		Section A	Section A Initial Action Des Chief Eng Chief		otion Sign & Date			on C	Chief Eng	QC Inspector		
							e.					

## Work Order ID 58242

Sunday, May 02, 2010 1:11:02 PM



Page 2

Item ID:

D3914-7

**Revision ID:** Item Name:

Rib

**Start Date:** 

5/3/2010

Req'd Qty: 6.00

Accept

Setup Start

Stop



Start Qty: 6.00 **Cust Item ID:** Required Date: 5/7/2010 **Customer:** 

Reference:

Approvals:

QC:

Process Plan:

Memo

Date:

Date:

**Tooling:** SPC (Y/N): Date:

Draw

Number

Date:

Draw

Rev.

Plan

Code

Accept

Qty

Start

Stop

Sequence ID/

Work Center ID

130

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ Run Hours

0.00

0.00

Run

Reject

Qty

Reject Insp.

Number Stamp

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHAI		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	•	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	<b>A</b> :	Date:				
	Re	esolution:	Disposition	QA: N/C Cld	QA: N/C Closed: Date:							
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	)						
DATE	STEP	Description of NC Section A	Initial Action Described Chief Eng Chief Eng		Section B tion Sign & Date		ation on C	Approval Chief Eng	Approval QC Inspector			
					i							

## **Picklist Print**

Sunday, May 02, 2010 1:11:01 PM

Work Order ID: 58242

Parent Item:

D3914-7

Rib Parent Item Name:

IPP Rev:A new issue DD 10.03.19 verified by:EC

**Start Date: 5/3/2010** 

Required Date: 5/7/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
M304TS0.500W.049		Purchased	No			100	f	260.6430	7.875	SAO	10-0	 5 -02
Square Tubing	:									<u> </u>		<u> </u>

Comments:

Location	Loc Oty	Loc Code
	Dot VII	<u>Loc Cour</u>
MAT	241.1124	
114426	241.1124	
MAT018	19.5306	
114004	3.5	
114161	16.0306	

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			,					11.64.64				
Part No: PAR #:			Fault Ca	tegory:		_ NCF	R: Yes	No <b>DQ</b>	۹:	Date:	····	
Resolution:			Disposition: Q				QA: N/C Closed: Date:					
NCR:			WORK OR	DER NON	-CONFORM	ANCE	(NCR	3)				
DATE	STEP	Description of NC				tion B	C: 0	Verific		Approval	Approval	
		Section A	Initial Chief Eng	ACU	on Description Chief Eng		Sign & Date		on C	Chief Eng	QC Inspector	
										1.18.1		
								:				
					- '							
		·				į						
	1											



W/O:			WO	RK ORDER CHA	NGES	<del> </del>	,					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No: PAR #:		PAR #:	Fault Category: NO				NCR: Yes No DQA: Date:					
Resolution:			Disposition:			: N/C Clo	sed:		Date: _			
NCR:			WORK ORDER NON-CONFOR				)			<del>-</del>		
DATE	STEP	Description of NC		Corrective Action Section B			Verific		cation Approval	Approval		
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	ion	Sign & Date	Section		Chief Eng	QC Inspector		
		, , , , , , , , , , , , , , , , , , , ,			•	***************************************	<del> </del>					
				•								
				·								
		· · · · · · · · · · · · · · · · · · ·								•		
٠.												